

CLASSIFICATION CONFIDENTIAL

CENTRAL INTELLIGENCE AGENCY

INFORMATION REPORT

COUNTRY Czechoslovakia

SUBJECT Bratislava Port Facilities on the Danube

PLACE
ACQUIREDDATE
ACQUIRED

DATE OF

CD NO.

DATE DISTR. 5-MAR-54

NO. OF PAGES 2

NO. OF ENCLS. 1
(LISTED BELOW)SUPPLEMENT TO
REPORT NO.

50X1-HUM

50X1-HUM

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES, WITHIN THE MEANING OF TITLE 18, SECTIONS 793 AND 794, OF THE U.S. CODE, AS AMENDED. ITS TRANSMISSION OR REVELATION OF ITS CONTENTS TO AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW. THE REPRODUCTION OF THIS PAGE IS PROHIBITED.

THIS IS UNEVALUATED INFORMATION

50X1-HUM

the Czechoslovakian Danube River Transportation Company
The headquarters of this organization were located at Bratislava.

2. An oil refinery located in the northwest corner of the dock area was destroyed during World War II but by 1948 this had been completely rebuilt. All other buildings that had been damaged had been repaired and were operating.
3. There were 18 warehouses in the dock area, all of one-story construction. These were all dry storage buildings. There were no facilities for cold storage. Various types of goods were stored in these warehouses that were awaiting shipment or transshipment. Oil storage tanks were located to the southeast, well out of the area, for protection. Each tank had a capacity of about eight hundred tons each. The river ships would be drawn up to the oil storage area, anchored, and then the oil would be pumped into the tanks by means of a pumping station.
4. Two boat basins had been constructed just off the river proper. The one to the south was known as basin No 1, and the one to the north, basin No 2. Basin No 1 had a skid system of three skids that were used to raise ships out of the basin for repairs. Machine shops for small and large repairs were located to the west and south of basin No 1.
5. There was one large crane of about 10-ton capacity located on the Danube proper. All other cranes in the area were five-ton capacity. There was also a grain elevator located on the Danube, south of basin No 1. This elevator was used for a short time in 1945 and 1946 to handle UNRRA wheat.
6. An army guard of about 10 men were billeted in a barracks in the area, their duty to guard the dock facilities.

50X1-HUM

50X1-HUM

50X1-HUM

50X1-HUM

CLASSIFICATION CONFIDENTIAL

DISTRIBUTION									
Navy Div.									

CONFIDENTIAL/

-2-


50X1-HUM


7. The port at Bratislava could load and unload about 12 ships and barges a day, each ship containing from six to seven hundred tons. A total of about six oil tanks could be loaded each twenty-four hours, for a grand total of thirty-six hundred tons.
8. The shipping organization carried steel, coal, and manufactured goods out of Bratislava and brought in tobacco, wine, iron ore and oil.


50X1-HUM


CONFIDENTIAL/

Page Denied











50X1-HUM

PORT FACILITIES

BRATISLAVA, CZECHOSLOVAKIA

1948

Scale - (Approx.) 1 inch = 0.80 yds

